GOVERNMENT OF ANDHRA PRADESH
ABSTRACT

Public Services – Treasuries and Accounts Department- Repair Works to Sub Treasury Building, Bandar, Machilipatnam, Krishna District – Administrative sanction- Orders – Issued.

FINANCE (ADMN.I) DEPARTMENT

G.O.RT.No. 185 **Dated: 03-02-2021.**

Read the following:-

1. DTA e-File No: FIN02-15069/4/2020 SEC-DTA(Computer No:1090879)
2. Rc.No.A3/4456/2010 dt.25.11.2020 of DD(FAC),DT, Krishna District.

<<>>

O R D E R:

In the reference first read above, the Director of Treasuries and Accounts, Ibrahimpatnam has stated that the DD(FAC), District Treasury, Krishna District has informed that the STO Building at Machilipatnam is submerged in rainy season to one foot level since the floor level of Sub Treasury Office, Machilipatnam is at low level than the adjacent road level. The Executive Engineer, R&B Division, Machilipatnam has furnished detailed estimates for an amount for Rs.3.30 Lakh to take up the urgent repair works of Sub Treasury Office, Machilipatnam. The DTA, Ibrahimpatnam has requested to accord administrative sanction for Rs.3.30 lakhs to take up the repairs of the building.

2. Government, after careful consideration of the proposal, hereby accord administrative sanction for Rs.3.30 lakhs to take up the repairs works of the said building under the Head of Account 2059-Pubic Works, 01-Office Works, 053-Maintenance and Buildings, 17-Buildings of Treasuries, 270-Minor Works, 271-Other Expenditure from the Budget provision available in current financial year 2020-21.

3. The Director of Treasuries and Accounts, AP., Ibrahimpatnam shall take further necessary action in the matter.

4. This order is available online and can be accessed at https://goir.ap.gov.in.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

SHAMSHER SINGH RAWAT
PRINCIPAL SECRETARY TO GOVERNMENT

To
The Director of Treasuries & Accounts, A.P, Ibrahimpatnam.
Copy to
SF/SC's (1098292)

//FORWARDED :: BY ORDER//

SECTION OFFICER